


Above Ground Pool Bonding Information

#8 Solid Copper Bond Wire – to be 18 in. – 24 in. away from the wall of the pool & must be buried 6 in. deep.

Pool frame ribs (legs)



*If a metal ladder is being used, the ladder must be bonded as well.

Copper Lugs (rated for direct burial) mounted from bond wire to frame ribs with stainless steel screws in 4 locations (preferably spaced evenly around pool).